

### APPLICATION STORY



## ASSESSING TREE HEALTH WITH INFRARED

The need to assess the overall health of trees is a growing requirement in property and environmental management. As trees in public spaces grow, their structure needs to be managed to preserve both property and public safety. Facilities managers and local authorities therefore have the task of balancing acceptable risk with the need to maintain tree stocks to enhance the environment and conserve nature. With the use of infrared technology, examining trees become a quick and cost efficient task.

The traditional methods of obtaining information on the health and structural status of a tree, in order to make these management decisions, are time consuming. Generally the assessment is far from holistic and invasive testing is often required. With these factors in mind a new company, Tree Project Limited with its origins in Nottingham Trent University, has developed high quality and sustainable tree management systems that are quick, easy and cause no harm to the tree. And its techniques are saving its clients significant time and money.

For the purpose Tree Project Limited uses FLIR thermal imaging. As company founder, Dr. Marcus Bellett-Travers explains, "This technology is ideal as it is the only non-invasive method that can distinguish between living and damaged stem tissues. It is also 100 to 1000 times quicker than other techniques at providing the necessary information. Because it's so fast, it's highly cost effective."

#### EXAMINING UP TO 100 TREES IN ONE DAY


He continues, "We can provide detailed health appraisals of the trunks and branches of up to 100 trees in a single day. And when a localised part of the tree is of interest, such as identifying basal decays in trees, that total can amount to several hundred trees. Also, measurements are made without the need to climb trees or to break through the protective bark layer or reaction zones."

# SEE DAMAGES AND DISEASES INSIDE THE TRUNK

Trees produce very low metabolic energy by comparison to other living organisms. This means most of the heat energy emitted from the surface of the trunk and limbs has previously been absorbed from the environment. Sound, healthy wood has good connectivity and water distribution between cells. This is seen by the FLIR infrared camera as even heat dissipation over the tree's surface.


If the normal function of the wood is disrupted by physical damage or the action of pathogens the flow of heat is interrupted





Beech tree with a central decay (blue areas) and sound wood in the buttresses (red areas).





and cooler areas become apparent; the greater the extent of cooling on an internal volume of wood, the greater the effect on the temperature at the surface.

#### A THERMAL BENCHMARK DATABASE

To create a thermal benchmark database Tree Project initially imaged 400 trees. Today that reference library sits at more than 35,000 trees and is subject to continuous updating. Using a new comparative image technique that it has now developed the company is also able to calculate the thickness of healthy wood to show a damaged tree is responding to surgery and treatment. Tree Projects Limited predominantly uses a FLIR P-Series camera, a model more often used for the factory form of plant maintenance! The company has also invested in a top of the range FLIR B-Series camera. This product is aimed at building diagnosis but is highly appropriate for tree health assessment as it is designed to operate in a smaller temperature band. It is therefore possible to see small temperature variants of  $1 - 2^{\circ}$ C.

#### CALCULATE THE TREE HEALTH STATUS

Once images have been captured on the cameras they are processed using

Tree Project's special Tree Thermal Matrix Software - TTMS<sup>™</sup> - that was created using the Software Developers Kit supplied by FLIR. This allows a percentage of dysfunction to be assigned to a tree and this in turn can be used to calibrate probability of failure. Wind loading is subsequently factored in as a further potential contributor to failure based on a five point scale created using Met Office data. A risk categorisation of low, moderate, high and severe can then be applied to the tree.

#### ANALYSING HOW FUNGI AFFECT TREES

Infrared is also being used by Tree Project in combination with partial root excavation to obtain information about diseases without damaging the root system. "This technique continues to improve our understanding of how trees interact with the fungi that remove wood through the decay process," Dr. Marcus Bellett-Travers continues. "Many of the fungi that were once thought to only damage trees have been shown by this process to have little effect on its performance. In fact it can actually improve it."

Although the majority of Tree Project clients taking advantage of infrared are in the local authority sector and pursuing a health and safety remit, others focus on the conservation of historic trees. Woburn Abbey, The National Trust and Blenheim Palace are typical examples. Dr. Marcus Bellett-Travers concludes, "Infrared is ideal for this type of work as it allows us to proactively maintain the health of important tree specimens."

For more information, visit www.flir.com/thg or contact:

#### FLIR Sweden

World Wide Thermography Center Rinkebyvägen 19 - PO Box 3 SE-182 11 Danderyd Sweden Tel.: +46 (0)8 753 25 00 Fax: +46 (0)8 755 07 52 e-mail: sales@flir.se